

Menu


HISTORY FILE MAP for year 1999

Realtime

Playback

Recalled Realtime

Recalled Playback



40m RT 4096bps plus 9m RT 512bps and 2h04m PB 512bps data lost due to DSS42 maser failure. DSS34 came up quickly to support, reducing data losses considerably. DR A04065 refers.

19m RT 2048ps plus 39m PB 512bps data lost due to DSS34 antenna runaway. DSS43 came up quickly to support, reducing data losses considerably. DR A04071 refers.